

Approved For Release 2000/04/11 : CIA-RDP66B00597R000400080036-5

CLASSIFIED MESSAGE

SECRET

DATE 0120Z 27 MAY 65

ROUTING	
2	10
3	11
4	12
5	13
6	14
7	15
8	16
PRIORITY	

25X1A

TO [REDACTED]
FROM [REDACTED]

ACTION:

INFO :

IN 89443

TOR 0948Z 27 MAY 65

OPS 1-10 L

25X1A

25X1A

TO PRIORITY [REDACTED] INFO

CITE [REDACTED] 9362

25X1A

COMMO LOGS

25X1D

C335C/270008Z/385

25X1A

26

1. 770/711/32/12/NA/22/1005/1000
2. 100 PER CENT
3. X BAND LIGHT, S AND P BANDS HEAVY ACTIVITY

25X1A

1. 107
2. NO ACTIVITY. DID NOT PREFLIGHT PROPERLY AT END OF RUNWAY BUT THIS PROBABLY DUE TO BASE GCA.

25X1A

1. 106/111/101
2. NO ACTIVITY. DID NOT PREFLIGHT PROPERLY AT END OF RUNWAY BUT OK AFTER 20 TO 30 MINUTES OF WARM UP. SITUATION COVERED BY SEPARATE CABLE.

25X1A

1. MV 404
2. MUCH ACTIVITY.

EDD
RS
RP
KB
WC
DB
MM
[Handwritten marks]

SECRET

GROUP 1
EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

25X1D

██████████ (IN 89443)

S E C R E T

PAGE TWO

NO O/S ACTIVITY.

25X1D

██████████ DID NOT OPERATE PROPERLY AT TAKEOFF PLUS 20 MINUTES.
PILOT HEARD NO SIDETONE. GROUND READOUT CONFIRMED UNIT NOT
FUNCTIONING PROPERLY. PILOT RETUNED TO NO EFFECT. WAS
INSTRUCTED TO SWITCH TO ALTERNATE FREQ. UNIT THEN WORKED
PROPERLY. SET BEING CHECK.
ALL OTHER RADIO AND NAVAIDS SATISFACTORY.

END OF MESSAGE

S E C R E T